UNCLASSIFIED

AD NUMBER AD500152 CLASSIFICATION CHANGES TO: UNCLASSIFIED FROM: CONFIDENTIAL LIMITATION CHANGES

TO:

Approved for public release; distribution is unlimited.

FROM:

Distribution authorized to U.S. Gov't. agencies and their contractors;
Administrative/Operational Use; 05 NOV 1968.
Other requests shall be referred to Assistant Chief of Staff for Force Development (Army), Washington, DC 20310.

AUTHORITY

AGO D/A ltr dtd 29 Apr 1980 AGO D/A ltr dtd 29 Apr 1980



DEPARTMENT OF THE ARMY

OFFICE OF THE ADJUTANT GENERAL WASHINGTON, D.C. 20310

IN REPLY REFER TO

AGAM-P (M)

(14 Feb 69) FOR OT UT 684159

25 February 1969

SUBJECT: Operational Report - Lessons Learned, Headquarters, 52nd Combat

Aviation Battalion, Period Ending 31 October 1968 (U)

SEE DISTRIBUTION

1. Subject report is forwarded for review and evaluation in accordance with paragraph 5b, AR 525-15. Evaluations and corrective actions should be reported to ACSFOR OT UT, Operational Reports Branch, within 90 days of receipt of covering letter.

2. Information contained in this report is provided to insure appropriate benefits in the future from lessons learned during current operations and may be adapted for use in developing training material.

BY ORDER OF THE SECRETARY OF THE ARMY:

1 Incl as

KENNETH G. WICKHAM Major General, USA

The Adjutant General

DISTRIBUTION:

Commanding Generals

US Continental Army Command

US Army Combat Developments Command

Commandants

US Army War College

US Army Command and General Staff College

US Army Air Defense School

US Army Armor School

US Army Aviation School

US Army Civil Affairs School

US Army Engineer School

US Army Field Artillery School

US Army Infantry School

US Army Intelligence School

US Army Medical Field Service School

US Army Chemical School

Regraded unclassified when separated from classified inclosure.

DISTRIBUTION (Cont'd)

US Army Military Police School

US Army Missile and Munitions School

US Army Ordnance School

US Army Quartermaster School

US Army Signal School

US Army Southeastern Signal School

US Army Special Warfare School

US Army Transportation School

Copies furnished:

Office, Chief of Staff, US Army

Deputy Chiefs of Staff

Chief of Engineers

Chief of Research and Development

Assistant Chiefs of Staff

The Surgeon General

The Provost Marshal General

OSD(SA), Assistant for Southeast Asia Forces

Director, Weapons Systems Evaluation Group

Defense Documentation Center

Security Officer, Hudson Institute

Commanding Generals

US Army Weapons Command

US Army Flight Training Center

Commanding Officers

US Army Limited War Laboratory

US Army Logistics, Doctrine Systems & Readiness Agency

US Army Aviation Test Activity

52d Combat Aviation Battalion

DEPARTMENT OF THE ARMY
HEADQUARTED, 52ND COMBAT AVIATION BATTALION
AFO San Francisco 96318

AVGD-CC

5 November 1968

SUBJECT: Operational Report of 52nd Combat Aviation Battalion for Period Ending 31 October 1968, RCS CSFOR-65 (R-1) (U)

SEE DISTRIBUTION

1. Section 1, Operations: Significant Activities:

- a. (C) General: Report for period 1 August through 31 October 1968, submitted in compliance with USARPAC Reg 525-15, USARV Reg 525-15 and 17th CAG Reg 525-15.
- (1) Headquarters, 52nd Combat Aviation Battalion, LTC William C. Chamberlain, Commanding, remains at Camp Holloway, Pleiku, RVN. Inclosure 1 reflects Organizational Structure and Station List of subordinate units as of 31 October 1968.
- (2) There has been no change of mission during this period. The battalion continues to provide aviation support to Military Assistance Command, Vietnam; Fourth Infantry Division; Fifth Special Forces Group; 52nd Artillery Group; Republic of Vietnam II Corps; and other Free World Military Forces in the central highlands of Vietnam (see Inclosure 5). In addition, the 52nd CAB controls all activities and functions of Camp Holloway, Holloway Army Airfield and Kontum AAF.

b. (C) Personnel:

- (1) Awards and Decorations: During this reporting period, 1,968 awards were processed and 1,566 were approved and received. This included the receipt of six Silver Stars, forty-three Distinguished Flying Crosses and 1,338 Air Medals.
- (2) Command and Staff Changes: The following Command and Staff position changes took place during the quarter:

FOSITION	RANK, NAME, SVC NO (Incoming) (Outgoing)	\underline{D}_{t} , \mathbf{TE}		
BW XO	LTC James Burton, 071159 LTC Thomas L. Williamson, 081560	1 Sep 68		
.	TITO THOMAS II. WITTIAMBOIL, COLYOS			

FOR CT UT 684159 INCL 1

CONFIDENTIAL 1

DOWNGRADED AT 3 YEAR INTERVALS; DECLASSIFIED AFTER 12 YEARS. DOD DIR 5200.10

) port of 52nd Combat Aviation Sattalion ber 1968, RCS CSFOR-65 (R-1) (U)	for Feriod
BN S-1	MAJ Glenn G. Morgan, 04031245 MAJ Curtis D. Green, 05301686	7 Aug 68
BN S-2	LT Robert A. DiPadova, 05343555 CFT Leo F. Welsh, Jr., 05325194	2 Sep 68
BN S-3	MAJ Larry B. Aicken, 074042 LTC George E. Burnison, 079206	21 aug 68
BN S-4	CW3 Robert E. McKown, W2211130 WAJ Kenneth R. Cary, OF 113571	24 Oct 68
DPC	MaJ Donald A. Roberts, 04063815 LTC James Burton, 071159	1 Sep 68
DFC	MAJ Fyne A. Gramly, 081645 MAJ Donald A. Roberts, 04063815	24 Oct 68
BN SIG OFF	CFT Terry A. Gunter, 05536250 CFT George H. Gauger, OF 100692	27 Sep 68
EN SFTY OFF	1LT Glenn E. Spelis, 05339109 MAJ David L. Boivan, 05542617	. 9 Oct 68
CO, HHD	CPT Daryl R. Cagle, 05406244 CiT Charles.R. Rayl, OF 104242	8 Oct 68
CO, 52D SCTY DET	1LT Victor L. Coulter, 05344157 1LT Daniel A. Berry, 05338951	16 Oct 68
CO, 94TH MED DET	CPT Merill J. Mirman, 05460680 CFT Fred G. Margolin, 05542726	27 Aug 68
CO, 57TH AMC	MAJ Robert R. Williams, 04009865 MAJ William D. Gess, Jr., 082600	27 Aug 68
CO, 615TH TC DET	CFT Silas L. Beck, 05331255 CFT Hubert G. Smith, 095757	26 Sep 68
CO, 822D SIG DET	CW2 Bernard J. Leftault, W3431107 CW2 Harvey Baker, Jr., W3431194	8 Oct 68
CO, 119TH AHC	MAJ Kenneth R. Cary, OF 113571 MAJ Warren R. Porter, 04422475	24 Oct 68

2

INCL 1

AVGD-CC (5 November 1968)

SUBJECT: Operational Report of 52nd Combat Aviation Battalion for Period Ending 31 October 1968, RCS CSFOR-65 (R-1) (U)

co,	545TH TC DAT	Ronald L. Dean, 05240428 Hugh H. Rhodes, OF 105523	10	Aug	68
CO,	170TH AHC	Donald A. Roberts, 04063815 Carl R. Jones, 02266308	24	Oct	68
co,	179TH ASHC	Donald E. Holroyd, 076235 Robert E. Wetherbie, 04047425	10	Sep	68
co,	189TH AHC	Robert N. Morrison, 04063784 William W. Fraker, OF 117169	.3	Oct	68
ÇO,	604TH TC DET	Ronald L. Collins, W3156446 Robert R. Stratiff, 04030843	25	Oct	68
co,	361STC(E)	Robert J. Rodgers, 078611 Larry B. Aicken, 074042	6	aug	६९

(3) The anticipated input of personnel during the month of September was programed to off-set the large number of known losses in October and November. This anticipated input did not materialize. Therefore, this battalion, having received and continuing to receive large numbers of replacements in October and into November will exceed the precent authorized losses per month in October and November 1969, creating additional infusion problems. These replacements have not off-set losses. The present shortages, coupled with the known losses for November are of particular concern to this command. Personnel turnover for the reporting period was as follows:

	<u>0/12.</u>	LISTED M	<u>112.</u>	OFFICE	R/WARRAN'	T OFFICER
MONTH	LUSS	G_{c} IN	CH.INGE	<u>LOSS</u>	GAIN	CHANCE
AUGUST	116	77	- 39	21	16	- 5
SEI TAMBER	101	74	- 27	34	36	+ 2
OCTOBAR	204	120	- 84	67	55	-12
TOTAL	421	271	-150	122	107	-15

(4) The battalion is at 80.3% authorized strength, short 307 enlisted men and 73 officers/warrant officers, as of 31 October 1968. Unit strengths are shown in Inclosure 2.

AVGD-CC (5 November 1968)

SUBJECT: Operational deport of 52nd Combat viation Battalion for Period Ending 31 October 1968, RCS CSFOR-65 (R-1) (U)

- c. (C) Intelligence: The 3-2 Section continues to publish a daily Intelligence Summary of significant activities in the Pleiku-Kontum area. Intelligence information is gathered from II Corps and 4th Infantry Division G-2 offices, intelligence briefings from other supported units and mission reports submitted by aviators and air Mission Commanders. The S-2 Section also controls access to and movement of 700 Vectnamese personnel and 14 3rd Country Nationals upon Camp Molloway and Kontum AAF. An improved personal pass monitoring system was placed in effect on 1 September 1968.
- (1) Enemy activity: Attacks against Allied Installations during this quarter were primarily stand-off attacks by fire with 60mm and 82mm mortars, and 107mm, 122mm and B-40 rockets. Only one light ground attack at Kontum, best described as a perimeter probe, was made in conjunction with the mortar and rocket attacks. Following a slight increase in frequency in August and September, the number of attacks declined toward the end of the quarter. Significant activity during the period:

022100 Aug: 52nd Security Detachment patrol encountered and engaged 10 - 15 man NVA mortar team 12 miles NE of Camp Holloway. 52nd mortars and 361st Cobras fired on the NVA in support of the patrol. 1 NVA KIA and 1 NVA WIA were confirmed. One AK-47, Russian 8A30 binoculars and miscellaneous web gear were recovered on 3 Aug.

230200 Aug: New Pleiku AFB, 2 miles N of Camp Holloway, received 37 rounds of 122mm rocket fire, with 10 US WIA and four C-L7 aircraft damaged.

230200 Aug: 57th AHC at Kontum City Airfield, 23 miles N of Camp Holloway, received approximately 45 rounds of mixed 82mm mortar, B-40 and 122mm rockets. 10 US were MIA, one UH-10 received light damage and several buildings and tents were damaged.

230525 Aug: 57th AHC, again under 122mm rocket attack, received 12 rounds, one HVN was KIa, three US $^{\circ}$ Ia, one bunker damaged and two UH-1H aircraft received light damage.

250115 Aug: No section of Camp Holloway, including the 88th S&S Bn POL storage area, and the 604th TC Co (DS) was hit by 16 122mm rockets. Three US were WIA; one UH-1H lightly damaged; one \$\frac{1}{4}\$ ton truck, one 3/4 ton truck, two fuel bladders and 15,000 gal. of JT-4 were destroyed.

101125 Sep: 57th AHC at Hontum received 12 122mm rockets during • 15 minute daylight rocket attacks. One Ub MIn, one UH-1H received minor damage, several tents, two trucks (one 3/4 ton, one $2\frac{1}{2}$ ton) and 50% of telephone communication lines were destroyed.

AVGD-CC (5 November 1968)

SUBJECT: Operational Report of 52nd Combat Aviation Battalion for Foriot Ending 31 October 1968, RCb CSFOR-65 (R-1) (U)

120057 Sep: 937th Engineer compound, NE of Pleiku City, had 29 US WI by an unknown number of 122mm rockets.

142400 Sep: 57th AHC and A-2/1st Cav were attacked by 82mm mortars and a ground probe of the 2/1st perimeter. Forty rounds of mortar fire inflicted light damage to three UH-1C and two UH-1H aircraft, destroyed six perimeter lights and two US WIA.

210205 Sep: New Pleiku AFB had three US WIA and seven buildings and three C-47 aircraft heavily damaged by 20 rounds of 107mm rocket fire.

211400 Sep: 189th AMC UH-1H was hit by NVA B-40 rocket fired from the edge of a landing zone at ZA 027719, 20 miles NW of Pleiku City. Aircraft crashed and burned, one US KIA and two WIA.

211700 Sep: Another 139th UH-IH hit by B-40 rocket in the same LJ, crashed from 30 feet and burned. Three Ub were VIa.

242255 Sep: 57th AHC received nine 122mm rockets which destroyed one tent, inflicted light damage to eight UH-1H and heavy damage to two UH-1H aircraft, Four trucks, two radios and various equipment were damaged and one US WIA.

292220 Sep: Connel Quarry, $1\frac{1}{2}$ miles is of Camp Holloway, was mortared with approximately 40 rounds of 82mm. Minor damage was incurred during the attack, which ceased as counter-mortar and gunships were employed.

252235 Oct: 937th Engineer compound again attacked by mortar fire, receiving 47 rounds of 82mm. 17 US WIA; one building and 27 vehicles were damaged.

311300 Oct: Enemy cache at AR 902720, 18 miles No of Camp Holloway, was captured by RVN units supported by 52nd CaB aircraft which evacuated 2,000 blasting caps; 100 lbs TNT; 6 recoilless rifle rounds, 30 rds 107mm, 73 B-40 and 15 rds B-41 rockets; 175 rds 60mm mortar; 35 assorted US and Chi Com mines; 60 hand and 70 rifle grenades; 107 boxes AK-47 ammunition and other enemy equipment.

(2) Movement: During the months of September and October, the 24th NV. Regt moved west to the Tri-Border area from its former position east of HWY 14 and north of Pleiku City. It was presumed that the Regt was forced to move to the border due to severe losses from B-52 strikes. During the reporting period there was a general movement to the west of all major NVA units. It is believed that these units are now in Cambodia and Laos refitting and recuperating.

NGD-CC (5 November 1968)

SUBJECT: Operational report of 52nd Combat venture pottation for region and any 31 October 1962, RCS CSFOR-65 (R-1) (U)

- (3) New Units: There have been no confirmed reports of new units in the Kontum/Tleiku Provinces in the last 3 months. There were several unconfirmed reports of a suspected armor unit 35-40 miles WSW of Fleiku, near the Cambodian border.
- (4) New Weapons: During the reporting period there have been sightings of unidentified rotary wing aircraft. The first sighting was made in late September. The sightings were made by radar and all occurred near the Tri-Border area. We actual visual sightings have been made though unidentified red rotating beacons have been observed. It is believed that these aircraft are being used to ferry high ranking Wa officers. Toward the end of October these reported sightings have increased. Enemy armor, though suspected to be near the border, has not been confirmed.

(5) Situation:

- (a) Kontum: The 40th Art's Gp is still located in the Tri-Border area approximately 50 km MM of Kontum City. The K-30 Bn/40th Regt is north of Polei Kleng, 20km M of Kontum. The K-32 Bn/40th Regt is SW of Ben Het operating in conjunction with the 101st NVA Regt located W of Dak Seang. The 406th Sapper Bn is presumed to be NM of Kontum City and the 28th Sapper Bn 20km SW of Kontum City.
- (b) Pleiku: The 407th and 408th Sapper Bn's are located approximately 15-20 km NE of Pleiku City. The 24th NVA Regt previously located east of HWY 14 and north of Pleiku City appears to have moved west into Cambodia. The 304th LF Bn is approximately 25km west of Flei Mrong and 8km north of Plei Djereng. The K-31 Bn/40th Regt is along HWY 14, 29km north of Fleiku and the H-15 LF Bn is along 2 of 19, approximately 10km east of Duc Co.

(6) Capabilities:

- (a) Kontum Province: The enemy has the capability to conduct ground attacks against US/Allied bases in the vicinity of Dak Seang, Ben Het, and Dak To with up to multi-battalion strength, supported by RR, mortar, rocket and artillery fire, with the possible use of armor. He can also conduct stand-off and sapper attacks against Kontum City and interdict highways QL 14N, 512 and other major friendly lines of communications.
- (b) Pleiku Frovince: The enemy has the capability to selectively attack Duc Co, Plei Djereng, Flei Mrong or Plei Me CIDC Camps and Edap Enang, Thanh an and Le Trung villages. He can conduct stand-off and sapper attacks against Pleiku City and Allied installations along highways L 19E and OL 14N and interdict highways 509, TL 60, 437, TL 70 and LTL 7B

AVGD-CC (5 November 1968)

SUBJECT: Operational Report of 52nd Combat Aviation Battalion for Feriod Ending 31 October 1968, RCb CSFOR-65 (R-1) (U)

with a company size VC elements, employing small arms, automatic weapons; recoilless rifle, rocket and mortar fire, as well as mines and anti-tank grenades.

d. (C) Operations: The priority mission of the 52nd Combat Aviation Battalion during this quarter was to provide aviation support to the 4th Infantry Division. This support was provided by the assets of two helicopter companies (UH-1) and one assault support helicopter company (CH-47) daily for 92 days. Operations Profrie Fire and Omega were supported by one assault helicopter company for 92 days, and by An Escort Helicopter Company (AH-1G Cobras) for 61 days. The Highway 19 Coordinator was supported by one UH-1H and four gunships (UH-1C/AH-1G) for 92 days. Task Force Spoiler was supported by the 170th AHC (OFCON 10th CAB) for a period of 42 days, and by other 52nd CaB units for 25 days. The 355th aviation Company (Heavy Helicopter) provided CH-54 support on a mission basis until it was reassigned to the 268th CAB on 15 September. One platoon of the 355th continues GH-54 support under Operational Control of 52nd CaB. Though hampered by monsoon weather that grounded all operations for three days early in the quarter, the battalion flew over 30,000 hours during the period, including 8,616 hours of Combat Assaults. Battalica aircraft also performed Chemical, Fire Support, Med-Evac, Combat Re-supply, Command and Control, Reconnaisance, Liaison and Administrative missions throughout the II Corps Tactical Zone, from Dak Fek south to Nhon Co and from the South China Sea west to the Cambodian and Laotian borders. Of particular interest are the Chemical Missions being flown in the 4th Div ...O. Terrain does not permit effective employment of C-123 "Runchhands" for aerial spraying operations, particularly in the 1st Brigade area of operations. Both UH-IH and CH-47 assets have been used extensively for defoliation, crop destruction and CS agent drops under the supervision of 4th Division Chemical Officers on board the dispensing circuaft. A UH-1H with the Airborne Fersonnel Detector (APD) "Feople Sniffer", escorted by UH-1H gunships, is used to search out concentrations of VC/ NVA on known infiltration and resupply routes. Other missions have been hampered, however, by inadequate planning and false assumptions. Ground commanders exhibited an apparent lack of knowledge of the capabilities, limitations and maintenance support requirements of army aviation. The continued selection of small (single ship) landing zones, lack of constant improvement of Fire Support Base helipads, and troops apparently not aware of basic safet/ procedures for heliborne operations have created undesired hazards. Combined with the low experience factor of most aviators assigned in September and October, these situations produced unacceptable hazards to aircraft, crews, passengers and troops on the ground. Command and staff liaison visits have overcome most problem areas, however, a shortage of qualified personnel has not allowed full-time liaison officers to assist supported brigades in air movement planning and efficient

7

AVGD-CC (5 November 1968)

SUBJECT: Operational Report of 52nd Combat Aviation Bratalion for Versod Unding 31 October 1968, RCS CSFCR-65 (R-1) (U)

scheduling of aviation assets. Coordination has been effected by assigning a liaison officer to the 4th Infantry Division and frequent visits with the Division C-3 and brigade commanders by the Commandine Officer, 52nd C.B. Continuity in support of a particular brigade has been increased by tasking the same aviation company to provide this support for a 30 to 60 day period. This permits the aviation company commander to become knowledgeable of the ground situation and to provide more efficient and effective support. The brigade commanders were able to capitalize upon the experience and recommendations of the company commanders specifically when the Brigade aviation Officers lack experience. IFFV directed missions, special request allocations and 52nd Battalion Area Movement Control Center scheduling have provided additional aviation support to the Us Air Force, II Corps Ban, 23rd ANN Div, Capital ROK Inf Div (CRID), 173rd Airborne Brigade, 5th Special Forces Group, 52nd artillery Group, 24th Special Tactical sone, Fleiku Sub area Command, Heiku Sector, Kontum Sector, 937th Engineers, 43rd Signal En, 125th .TC Co and the IFFV Iress Camp. Technical representatives (Tech Reps) of Bell Helicopters, Lycoming Division, Dynaelectron Corporation and the Federal Aviation Administration, as well as American Red Cross, U30 and Special Services personnel were transported by the 52nd C.B. Statistical results of operations are shown in Inclosure 3.

- e. (U) Training: On the job training in all NOS fields has been employed by battalion units and sections throughout the quarter. Classes required by Training Directive 350-1 have been conducted and an active replacement training program continues. Additional gunship pilots have been qualified with the KM-429 proximity fused 2.75 rocket and with the AM 229 171b warhead. Other aviator training and standardization is included in paragraph li of this report.
- (1) 2.75" FFAR IDU-4A/A (Flechette) training for elements of the 52nd CAB, 7/17th Cav, 4th Inf Div, 17th CAG and 16th CAG was conducted by the Flechette New Equipment Test Team. With the 52nd CAB providing classroom and briefing facilities, a firing range, transportation and coordination, the 361st Avn Co and METT instructors qualified over 30 gunship pilots and instructor pilots in the techniques required for Flechette employment. Over 200 personnel received ground instruction on storage, handling, characteristics and effects of the warhead. This qualification period, from 18 through 25 October 168, was the training highlight of the quarter.
- (2) Personnel from the 355th Avn Co presented a rigging class and briefed members of the 3rd Brigade, 4th Infantry Division on proper methods and equipment used to prepare sling loads for heavy helicopters. Approximately 30 individuals attended this briefing on 9 October 1968.

SUBJECT: Operational Report of 52nd Combat Aviation Battalion for Period Ending 31 October 1968, RCS CSFOR-65 (R-1) (U)

- (3) The CH-47C NETT arrived at the 179th Assault Support Helicopter Company on 2 October 1968. During periods of ground and flight training, the team qualified unit aviators in the improved Chinook and familiarized maintenance crews with the general characteristics and field maintenance procedures required. Major roints stressed in both training programs were the increased speed and greater cargo capability of the CH-47C over the "A" model currently assigned to the 179th Assault Support Helicopter Company.
- (4) The 361st Aviation Company (Escort) completed in-country qualification in the AH-1G Cobra at Bein Hoo during August. During the initial qualification period, one pilot was qualified as an Instructor Filot and later as a Standardization Instructor Filot by the NET Team. Ground support personnel were qualified in rearming procedures, ground safety, and aircraft, armament and Stability Augmentation System maintenance for the AH-1G.

f. (C) Logistics:

- (1) Supply: Staff supervision realignment during the reporting period has brought several additional activities into S-4 channels.
- (a) The motor maintenance officer was placed under the S-4 to stream-line reports and procedures required by AR 711-5. An increase in accuracy of Material Readiness reports has already been realized. The motor officer has also initiated prescribed load list (FLL) inspections throughout the battalion supply system. This inspection has allowed many requests to be consolidated, cancelled or reordered as required by new equipment arriving in the units.
- (b) Due to a shortage of company Quartermaster Property Book Officers, (QMFBO) a battalion QMPBO has been assigned to the S-4 Section to assist units with property book problems. He assists units in maintenance of supply records, advises on procedures, keeps the commander informed of battalion assets, shortages, and problem areas. The Bn PBO has established systems for units to reduce the time required to fill unit requisitions by hand carrying consolidated requests forward during linison visits to supply depots.
- (c) The S-4 Section now includes a Battalion Ammunition Warrant Officer. The Bn Ammunition Officer maintains consolidated records of ammunition availability, expenditure and lot numbers of condemmed or restricted ammunition. Other units have experienced accidental firing of restricted lots of ammunition that should have been removed from the

AVGD=CC (5 November 1968)
SUBJECT: Operational Report of 52nd Combit Aviation buttalion for Ferrod Ending 31 October 1969, RCS CEFOR=65 (R=1) (U)

supply system. This battalion deemed it necessary to create this position to preclude similar type accidents. The Ammunition Officer inspects the unit's Class V records, storage areas, and visits the pre-stock points throughout the area of operation. The quantity of ammunition required by the 52nd CAB for basic loads, combat operations, base camp defense, and training is comparable to that required by a medium Artillery battalion.

- (2) Vehicle Maintenance: A vehicle maintenance standdown program was initiated in October to improve ground transportation availability. Each wheeled motor vehicle within the battalion is scheduled for concentrated operator maintenance one day per week. Trailers are scheduled for monthly intensive maintenance under this program, which is supervised by section chiefs and unit maintenance personnel. A printed checklist for operator maintenance is used for each type of equipment. Roadside spot inspections, reports and RBI's help to add command emphasis to this program.
- (3) Class III: 52nd CAB dispensed a total of 1,351,000 gallons of JP-4 fuel during the reporting period, including 496,000 gallons dispensed by the 57th Assault Helicopter Company of Montum City Airfield.
- (4) Class V: aircraft ammunition expenditure for the quarter is listed below:

2.75" FFAR 6,767 rds 40mm Grenedes 9,395 rds 7.62mm (Mini-gun) 1,428,600 rds

g. (U) Aircraft Maintenance:

(1) During the reporting period, the 52nd Combat Aviation Battalion and the 604th Transportation Company (DSU) established a monthly Maintenance and Supply Seminar. The objective of the seminar is to establish liaison and coordination between all maintenance units located in the Pleiku area; improve working relations between the direct support unit and units of the 52nd CAB; project maintenance work loads and requirements of battalion units; discuss problem areas and ways to increase aircraft availability; and establish and maintain a rigid tech supply reconciliation program with the DSU tech supply in order to expedite EDP's and normal requisitions. The 604th Transportation Company (DSU) acts as the host unit each month and requires the supported units to submit data for discussion. Each unit of the battalion participates and requires the Maintenance Officer, Tech Supply Officer, and key maintenance NCO's to attend. This program has been in effect for two months and is considered to be a key step in improving maintenance operations by all maintenance personnel.

AVGD-CC (5 November 1968)

SUBJECT: Operational Report of 52nd Combat ..viation Battalion for Puriod Ending 31 October 1968, RCS CSFOR-65 (R-1) (U)

The seminar provides the operaturity for the maintenance personnel to exchange ideas on procedures and thereby aiding in the dissemination of the latest maintenance information.

(2) Maintenance Statistics:

	AH-1G	<u>CH-47A</u>	<u>uH-1C</u>	UH-1D	UH-1H	<u>U-6</u> A
Aircraft Authorized	12	16	32	2	93	1
Total Aircraft Assigned	12	14	29	1	78	ı
Average Aircraft Per Co	12	14	7.5	l	19.5	1
Avg lability Rate (%)	68	58	75.1	90	75.5	go.6
EDM Rate (%)	14.5	31	19.7	10	17.6	19.4

See Inclosure 4 for Aircraft Status and Flying Hours.

h. (U) Accident Prevention:

- (1) The battalion compiled a record 101 days of accident-free flying which terminated on 23 September 1968. During that 101 day period, which was in conjunction with monsoon season, 47,679 flying hours were recorded with approximately 189,840 landings. In the final portion of this reporting period there were four aircraft accidents, three major and one minor. The following is a summary of the occurences during this period:
 - (a) 1-31 August 1968: Accident Free.
 - (b) 1-22 September 1968: Accident Free.
- (c) 23 September 1968: UH-1H, #67-17265, 119th AHC used a FZ with marginal rotor clearance to attempt to pick up the 5 remaining members of a recon team. The aircraft was required to hover due to the slope of the terrain and stumps. While 4 of the team louded on one side of the aircraft, the fifth one unexpectedly jumped on the opposite side causing an abrupt change in CG and accompanying control problems. The aircraft strack several trees with the main rotor before hitting the ground which resulted in a major accident.
- (d) 23 September 1968: UH-10, #66-14140, 170th AHC was over unfavorable terrain when the engine began to loose power. On short final to a vacated PZ, while executing a precautionary landing, the engine failed at

AVGD-CC (5 November 1968)

SUBJECT: Operational Report of 52nd Combat Aviation Battalion for Period Ending 31 October 1968, RCS CEPOR-65 (R-1) (U)

about 20 feet altitude and 20 knots air speed. The aircraft hit the ground hard with a forward speed of 10 knots. A combination of a hard landing and soft ground resulted in a minor accident. Fost accident inspection of the engine revealed that the engine had failed due to ingestion of dzuz fasteners from the inlet screen.

- (e) 5 October 1968: CH-47A, #66-19067, 179th AHC was hovering for takeoff on runway 23 at Holloway AAF when a rear blade sep rated from the aircraft. The transmission mounts severed, and the remaining blades struck the fuselage rupturing the fuel cells. The fuel ignited and the burning aircraft crashed on the runway coming to rest on its left side. The aircraft was a total lose. The cause of this accident was a blade socket failure.
- (f) 30 October 1968: UH-1C, #66-15140, 170th AHC was flying straight and level when it experienced anti-torque failure. Immediately the mircraft yawed to the right 30-40 degrees and banked to the right about 15 degrees. The aircraft commander was unable to level the aircraft with cyclic and he began a descent to about 150 feet absolute altitude and entered into autorotation. The aircraft commander was unable to maintain adequate ground reference during the turning descent and pulled pitch too late to prevent an extremely hard landing. The aircraft incurred major damage.
- (2) A dust prevention program has been implemented which will decrease engine erosion and non-scheduled maintenance. This program should reduce incidents due to loss of visual reference in blowing dust. Il aviators have been advised of the hazards that may be encountered in dusty environments. Also the units of the 4th Div supported by this battalion have a program which is coc dinated with our efforts in the area of dust suppression.

i. (U) Flight Standardization:

- (1) The Battalion Standardization Officer flew 88 hours qualifying new instructor pilots, administering 90 day standardization checks of unit instructors, and conducting irreraft commander check rides for battalion aviators. Lack of available training aircraft, especially UH-1C models, and a 30 day emergency leave reduced the amount of training conducted by the standardization pilot.
- (2) Approximately 40% of the unit instructor pilots have rotated during the reporting period. Some 90 day standardization rides have been delayed by lack of unit instructor pilots during the quarter.

AVGD-CC (5 November 1968)
SUBJECT: Operational Report of 52nd Combat Aviation Enttalion for Period Ending 31 October 1968, RCS CSFOR-65 (R-1) (U)

(3) Assistance by the 17th CAG Standardization Section and increased training aircraft availability in October has allowed new instructor pilots to be trained to replace the DEROS losses. At the end of the reporting period, the battalion has 24 instructor pilots, including standardization pilots, and the backlog of quarterly standardization rides experienced earlier in the reporting period has been eliminated.

j. (U) Organization:

- (1) Post Headquarters, under the direction of the Deputy Post Commander, continues to supervise and manage the non-tactical activities of Camp Holloway and Holloway army Airfield. Frojects completed during this period were:
- (a) Improvement of a new billeting area for the 170th Assault Helicopter Company.
- (b) Construction of a new control tower and installation of improved, expanded Air Traffic Control communications for the 344th Aviation Support Detachment.
- (c) The perimeter access road was improved so that a vehicle may travel the entire perimeter, thereby providing means to move bunker and construction material to the intended point of use.
- (d) All major roads, aircraft parking areas and FOL areas have been oiled or peniprimed to help control dust.
- (e) after six months, a 3 inch submersible pump was received and installed in a deep well at Camp Holloway. This provided a noticable increase in the water supply which enabled the previous restrictions on water utilization to be suspended. Additional pumps have been obtained and are awaiting installation.
- (f) The generators providing post lighting have been relocated throughout the post area in order to reduce the voltage drop due to extremely long wires. This also reduced the probability of having more than one generator damaged at any one time from hostile action.
- (2) The 170th AHC (-) was OPCON 10th CAB at Dong Ba Thin, RVN, from 24 August 1968 until 4 October 1968 to support Task Force Spoiler in the Ban Me Thuot area.
- (3) The 355th Aviation Company (Heavy Helicopter) was reassigned to the 268th CaB by 17th CaG GO 74, effective 15 September 1968. One platoon

AVGD-CC (5 November 1968)

SUBJECT: Operational Report of 52nd Combat Aviation battalian for Period Ending 31 October 1968, RCs CuFuR-65 (R-1) (U)

of the 355th Aviation Company (Heavy Helicopter) consisting of three CH-54 aircraft remained at Camp Holloway, OFCCN 52nd C.B.

(4) The 52nd Security Detachment and 68th Infuntry Ruder Detachment were attached to Headquarters and Headquarters Detachment with OPCON to the Deputy Fost Commander on 13 October 1968.

k. (U) Other:

(1) Chaplain:

- (a) During the quarter, Protestant Services were conducted by the battalion Chaplain both in the Chapel and in the 604th Trans Co Theater. Catholic Services were conducted by the Fleiku Sub Area Command Catholic Chaplain. Religious services for the 57th AMC at Nontum were conducted by the MACV Protestant Chaplain and the ARVN Catholic Chaplain stationed in that area. Physical improvements included A new tile floor and a new Hammond Organ for the 52nd CAB Chapel at Camp Holloway.
- (b) Civic action programs consisted of the distribution of excess produce and packaged foods, and salvage lumber to the Christian and Missionary alliance and the Catholic Orphanage, both in Pleika. A total of \$962.05 in special offerings was received and distributed to various agencies. Individual donations to specific causes totaled \$225.50.

(2) Surgeon:

- (a) A permanent dispensary has been built and stocked with improved medical equipment and supplies to provide better medical facilities to the 57th AHC at kentum.
- (b) A secondary emergency aid station has been established to support units on the north side of Camp Holloway. The aid station has various medical supplies, an ambulance, and is manned by two medical aid mon during alerts.
- (c) Over 90% of the troops at Camp Holloway received an influenza immunization during the month of October.
- (d) The diarrhea rate has decreased significantly during this quarter. This is attributed to better control of water supply, increased flow rate of wells and the reduced amount of terrestial water being used.
- (e) Although no specific MEDCAP program is in effect, medical personnel have actively supported the Pleiku Leprosarium, the Christian

AVGD-CC (5 November 1968)

SUBJECT: Operational deport of 52nd Combat ..viation Battalion for Feriod Ending 31 October 1968, (CS CSFOR-65 (R-1) (U)

Missionary Alliance Clinic, the Kontum Catholic Hospital and the Pleiku Catholic Orphanage.

- (3) Signal: During October 1968, the 52nd CAB Communications Section added the KYB-6 cipher system to the Area Movement Control Center radio. The battalion can now operate its Frequency Modulation Communications Net with secure voice transmission capability.
- 2. Section 2, Lessons Learned: Commander's Observations, Evaluations, and Recommendations:
 - a. (U) <u>Fersonnel</u>: Unit Strength Deficiencies
- (1) OBSERVATION: DEROS rotations and infusion losses without replacement on a 1:1 ratio will reduce the effectiveness of combat units.
- (2) EVALUATION: Reduction in the number of personnel in a unit requires a higher percentage of available troops to perform administrative details, guard duty and other related tasks which are not reduced. Personnel required to perform double duty cannot work efficiently over a long period of time. This is particularly true in the case of crewchiefs, gunners and direcraft maintenance personnel who must perform perimeter guard duty at night and, out of necessity, return to full duty the following day.
- (3) RECOMMENDATION: Frogram and assign replacements on a 1:1 ratio to known losses at all levels of command. Insure sufficient input into the 67N MOS program to fill these critical jobs. Provide infantry units to assist in the security of aviation units at isolated posts.
 - b. (C) Operations:
 - (1) Inadequate briefing for airmobile operations.
- (a) OBSERVATION: Injuries, fatalities and aircraft accidents have been caused by the improper and unsafe method used by troops to board and off-load helicopters, particularly in single ship landing zones.
- (b) EVALUATION: Ground troops have walked into rotor blades while approaching or departing helicopters during airmobile operations. They fail to recognize the dangers of sloped landing zones, departing the helicopter up-slope, against the directions of the aircrew. Troops attempting to board hovering aircraft in single ship landing zones have

AVGD-CC (5 November 1968)

SUBJECT: Operational Report of 52nd Combat Aviation Battalion for Feriod Ending 31 October 1968, RCS CUFOR-65 (R-1) (U)

caused loss of control and crashes due to the unexpected changes in the center of gravity of the direction. Crew directions have been ignored or disobeyed.

- (c) RECOMMENDATION: All units engaged in helicopter troop movements provide adequate safety briefings prior to actual operations. Instruct troops to approach or depart helicopters from the down-slope side, preferably from the front, and only upon direction of an aircrew member. Brief troops to remain seated until directed to off-load by crewmembers.
 - (2) LRRP Insertions and Extractions
- (a) OBSERVATION: Long Range Reconnaisance Patrol (IRAP) operations are put into effect with little coordination or planning between the supported unit staff and aviation elements.
- (b) EVALUATION: Frequently, LRRP insertions are planned by a unit S-2 without staff coordination to establish priorities for maximum utilization of available assets. Aviation elements are not included in mission planning. Aircraft are scheduled for the insertion or Class I and Class V resupply after normal missions are completed. Fatigued aircrews are required to accomplish these exacting flights, which may require 100 foot vertical descents and take-offs, in near darkness. Lat release times from these missions denies valuable daylight maintenance time to the aviation unit.
- (c) RECOMMENDATION: Employ the "Backward Flanning" sequence for LRRF missions at all levels of command. Establish priorities for aviation and logistics support early to permit daylight insertions and resupply of LRRF's. Include air mission commanders or aviation unit liaison officers in all phases of airmobile planning.
 - (3) Employment of MDU-4A/A Flechettes:
- (a) OBSERVATION: The WDU-4A/A Flechette rocket is a highly effective area fire weapon, but is not suited for use close to friendly personnel.
- (b) VALUATION: Following initial qualification by the USARV Flectette NET Team, the 361st aviation Company has been employing Flechette rockets. The tremendous area of coverage and penetration power of this weapon is ideal for landing zone proparation, post-extraction suppression and interdiction of enemy movement, but does not allow its use in close proximity to friendly elements. The AH-IG Cobra in the Hog configuration offers weapons selectivity from the cockpit, and can employ either Flechette or high explosive rockets as required by the ground situation. UH-IC armament systems do not offer this selectivity and must be armed with appropriate rockets prior to take off. Flechette employment by UH-IC is

AVGD-CC (5 November 1968)

SUBJECT: Operational Report of 52nd Combat Aviation Battalion for Period Ending 31 Octobe 1968, RCS CSFOR-65 (R-1) (U)

limited to pre-planned targets such as "people sniffer" escort and interdiction missions. Employment of the Flechette warhead by the following policy letter:

"QUOTE"

- 1. (C) The Flechette 2.75" WDU-4A/A warhead is released for operational employment, subject to the following restrictions:
- a. The flechette is not a close support weapon and will not be fired within 500 meters of friendly troops.
- b. Each aviator must be qualified in firing the Flechette by the NET Team or a qualified gunnery IP prior to tactical employment of the weapon.
- c. Aviators must insure proper loading and weapons selection to preclude accidental firing of Flechettes when HE is desired.
 - (1) Flechette and Hd rounds will not be loaded on the same UH-1C(A):
- (2) The use of a heavy fire team with one UH-1C armed with only Flechette rockets will allow proper control and selection of munitions by the Fire Team Leader.
- (3) AH-IG Cobras in the Hog configuration may be loaded with both HE and Flechettes, however all Flechettes will be on the same firing circuit (either inboard or outboard). Aviators will exercise extreme caution in the selection and employment of proper wing stores.
- (4) AH-IG Cobras in the Scout configuration will not carry mixed HE and Flechette warheads.
- 2. (C) Friendly positions and the characteristic dispersion pattern of the Flechette must be given special consideration to determine the proper direction of attack. Firing runs will not be made over or toward the positions of friendly troops.
- 3. (C) Flechette employment will be limited to the following:
 - a. Preparation of unsecure landing zones.
 - b. After final extractions are complete.
 - c. Neutralization of enemy base camps.
- d. Interdiction of known enemy movement. "UNQUOTE"

AVGD-CC (5 November 1968)

SUBJECT: Operational Report of 52nd Combat Aviation Battalion for Period Ending 31 October 1968, RCS CSFOR-65 (R-1) (U)

- (c) RECOMENDATION: Provide a selective weapon system capability for the UH-1C gunship. Increase the supply of WDU-4n/n (20 grain) warheads to units equipped with AH-1G helicopters. Arm the nH-1G in the "Mini-Hog" configuration, with HE rockets in IM-159 pods inboard, and MM-157 pods loaded with Flechettes outboard, for general support or reinforcing type missions.
 - (4) Area Movement Control Center (AMCC):
- (a) OBSERVIATION: AMCC concept is hampered by units misutilizing sole-user aircraft allocations.
- (b) EVALUATION: These units are employing aircraft without regard to conservation of engines, consolidation of missions, or adequate mission planning. A large number of previously AMCC missions have reverted to daily sole-user allocations. These can no longer be termed AMCC missions as AMCC has in fact no control over their utilization. These aircraft belong to the supported unit and are under their complete control. In the event an aircraft is not allocated to this AMCC daily committment for a full day, regardless of need, the supported units submit a report of unsatisfactory aviation support to the higher headquarters who then directs these requests to be filled. Sole-user aircraft are frequently extended beyond normal release time. Examples of misutilization of allocated aircraft are using UH-1H helicopters for cross-country flights from fixed wing to fixed wing airfields over a distance of 78 miles, and using UH-1H helicopt rs to provide convoy cover which should have required armed helicopters and/or other smaller observation aircraft. Through the efficient use of AMCC assets, the 5th Special Forces at Fleiku has moved over 535 tons of cargo per month without a daily aircraft allocation. This was accomplished by the unit having prepared loads prepositioned and requesting support on a mission basis.
- (c) RECOMMENDATION: Eliminate sole-user aircraft allocations, except for General Officers. Require mission schedules or itineraries to be submitted with daily aircraft requests. Encourage use of "mass transportation" instead of an "aerial taxi" concept for aviation support.

c. (U) Training:

- (1) UH-1 Emergency Procedures in Flight Training:
- (a) OBSERVATION: USAPHS and USAAVNS flight training stresses power-off procedures but does not adequately emphasize loss of directional control as an inflight emergency.

AVGD-CC (5 November 1968)

SUBJECT: Operational Report of 52nd Combat Aviation Battalion for Feriod Ending 31 October 1968, RCS CSFOR-65 (R-1) (U)

- (b) EVALUATION: During the last 90 days, this battalion has experienced four power failures and three tail rotor drive (directional control) failures. Relatively inexperienced aviators successfully executed power-off landings, but even more experienced pilots were unable to cope with loss of directional control. These tail rotor failures subsequently caused the loss of two UH-1 helicopters and injuries to three crewmembers. Following increased emphasis on directional control failure during standardization flights, unit aviators can cope with the various types of tail rotor failures as evidenced by two out of three successful landings after failure.
- (c) RECOMMENDATION: Increased emphasis should be placed on directional control emergency procedures in initial rotary wing training. Pilots should be trained to recognize and overcome each separate type of tail rotor failure.
 - (2) New Equipment Qualification:
- (a) OBSERVATION: AH-1G, CH-47C and WDU-4A/A New Equipment Test Teams are currently training combat units in Vietnam.
- (b) EVALUATION: Members of the 52nd CAB have received training at their home station from the CH-47C NETT and the DU-4A/A NETT. Aviators and ground personnel were adequately trained, using local flights and facilities, while maintaining uninterrupted mission response and combat effectiveness. The AH-1G NET Team conducted training only at Bien Hoa and required aviators to travel TDY to receive initial qualifications. This reduced the aviator strength of the armed helicopter company by approximately 25% for a 60 day period. Unit training at home station is preferred.
- (c) RECOMMENDATION: Deploy New Equipment Test Teams to unit locations when entire units must be qualified with new equipment. NETT Standard-ization Pilots should visit units in the field to administer IP standar-ization and check rides in new aircraft.

d. (U) <u>Intelligence</u>:

- (1) OBSERVATION: Control and accountability of Vietnamese civilians who do not display USARV passes on military installations is difficult.
- (2) EVALUATION: USARV Regulation 190-20 requires indigenous personnel entering or working upon US military installations to properly display identification passes on their person at all times. In the past, violation of this regulation has made identification and location of

AVGD-CC (5 November 1968)

SUBJECT: Operational Report of 52nd Combat Aviation Battalion for Period Ending 31 October 1968, RCS CSFCA-65 (R-1) (U)

Vietnamese civilians difficult while on post. After being cleared on post, local employees would remove their USARV passes and wander away from assigned work areas. The battalion S-2 has initiated a program to suspend employment of local nationals who do not display passes prominently while on post. First time violators are suspended for five days, second offenders are suspended for 10 days and automatic dismissal is mandatory for personnel with three violations of this regulation. Also, units employing Vietnamese are required to submit monthly civilian personnel rosters which list employees name, occupation, GVN identification number, USARV pass number and Camp Holloway gate pass number to the S-2. This permits control of the number, location and occupation of all Vietnamese civilians on post, and provides accurate data on civilian employment information.

(3) RECOMMEND ATION: Collect and disseminate similar procedures which allow units to improve internal security and counter-espionage measures on military installations in foreign nations.

e. (C) Logistics:

- (1) Team Concept Maintenance of AH-1G Helicopters:
- (a) OBSERVITION: Assigning provide ast possible utilization of assigned personnel.
- (b) EVALUATION: As AH-IG Cobras replaced UH-IC gunships, unit crow-chiefs were assigned responsibility for organizational maintenance on one aircraft as a non-crew member. Service Platoon and TC Detachment mechanics provided scheduled and non-scheduled maintenance support. The shortage of personnel and existing outside committments made this system inefficient and unacceptable. All personnel from the company and TC Detachment in MCS 67N were organized, not two similar work crews supervised by two platoon sergeants acting as shop foremen. Each work crew is on duty for a 12 hour shift, thus the company rotains 24 hours maintenance capability for daily inspection, cleaning, scheduled and non-scheduled maintenance. Work priorities are established by the TC Detachment Commander and supervised by the shop foreman on duty. This improved maintenance system has increased aircraft availability, allowed better utilization of maintenance assets and permitted more scheduled rest for crewchiefs and helicopter repairmen.
- (c) RECOMEND TION: Units assigned aircraft with non-flying crew-chiefs (AH-IG, OV-1, etc) should implement and evaluate the team concept of aircraft maintenance.

AVGD=CC (5 November 1968)
SUBJECT: Operational Report of 52nd Combat Aviation Battalion for Period Ending 31 October 1968, ECS CSFCR=65 (R-1) (U)

- (2) Forward Area aircraft baintenance:
- (a) OBSERVATION: Non-scheduled aircraft maintenance should be accomplished with minimum delay to assigned missions.
- (b) EVALUATION: During the course of a day, a significant number of aircraft working out of forward bases develop maintenance problems. Returning to base for repairs causes excessive delay in the accomplishment of assigned missions. A technical inspector, avionics repairman, armament specialist and anyeral helicopter repairmen can be carried to the forward staging area aboard aircraft assigned to support an operation. Most minor maintenance problems can then be corrected on the spot without returning to the base airfield. Non-productive flight time is minimized and aircraft availability is increased by this procedure.
- (c) RACOMMENDATION: Assault helicopter companies should establish mobile maintenance teams to accompany latoon size missions which stage out of forward bases without maintenance facilities.
 - (3) AH-IG Fluxmating Oil Pressure:
- (a) ORSERVATION: The AH-IG has had numerous instances of fluxuating engine oil pressure,
- (b) EVALUATION: After 15 to 50 hours of operation, the AH-IG engine oil pressure drops approximately 15 PSI and fluxuates 10 to 20 PSI. Contamination has caused the oil to foam, but the source of contamination is not yet identified by the Quartermaster oil analysis laboratory. Changing the engine oil eliminates the immediate problem and returns the Cobra to service, but this is not a complete solution. Both Bell Helicopter and AVCO Lycoming are investigating this problem.
- (a) RECOMMENDATION: Continue investigation to determine cause of the oil contamination and foaming. Change oil at every intermedia and periodic inspection as an interim measure.
 - (4) AH-1G Vibrations:
- (a) OBSETVATION: Cobra aviators report excessive vibration levels during high appeal maneuvers.
- (b) EVALUATION: Extensive vibration analysis and adjustment of recorblades, rotor head, friction collect and rotating controls has reduced the vibration level slightly. Primary cause of the vibration was found to be harmonic vibration of KM 1590 rocket pods which have failed internally.

21

AVGD-CC (5 November 1968)

SUBJECT: Operational Report of 52nd Combat aviation Battalion for Feriod Ending 31 October 1963, BCS CSFOR-65 (R-1) (U)

The internal metal bands holding the individual tubes together are breaking and the rockets and pods vibrate in harmony with the main rotor. The AM 1590 pods which fail can be used on UH-10 gunships which operate at reduced airspeeds and impose less stress on the pods.

- (c) RECOMMENDATION: Equipment improvement recommendations (EIR) have been submitted to strengthen the rocket pod internally. Inspect and replace rocket pods as required. Disseminate this information to all AH-IG units and activities.
 - (5) AH-1G/XM-15-C Swaybrace Breakage:
- (a) OBSERVATION: Cobra unit armament personnel report numerous broken swaybraces on AH-1G Cobras equipped with AM-1590 rocket pods.
- (b) EVALUATION: Swaybraces usually break at the forward inboard side of the rocket pod. These swaybraces, which are not aligned with the radius of the rocket pod, are broken by the side loads imposed on them by the pod. The swaybrace attaching lug on the bomb rack appears to be too thin to adequately support the swaybrace at the proper angle.
- (c) RECOMMEND TION: Modify the swaybrace attaching lug with thicker stock. Drill and tap swaybrace holes in line with the radius of installed NM-1590 rocket pod.
 - (6) AH-IG Hydraulic Accumulator:
- (a) OESERVATION: Hydraulic accumulation failure is caused by incomplete shut down procedures.
- (b) EVALUATION: Hydraulic accumulator internal failures occur when the hydralic system is bled only by pumping the collective pitch after shutdown. Seals deteriorate when the system is static if the hydraulic access panel is not removed and the accumulator bled through the connections provided inside the aircraft.
- (c) RECOMMENDATION: Advise AH-16 units and activities of the complete hydraulic bleeding procedure required by the Cobra. Units provide appropriate tools and training to allow aviators to perform this post flight procedure when maintenance personnel are not available.
 - (7) Aircraft Parts:
- (a) OBSERVATION: Requisitioned EDP parts frequently require more than 30 days to arrive at the requesting unit from USAAMC and 1st Logistical Command.

AVCD-CC (5 November 1968)

SUBJECT: Operational Report of 52nd Combat aviation Battalion for Period Ending 31 October 1968, RCS CSFOR-65 (R-1) (U)

- (b) EVALUATION: Aircraft have been grounded EDP due to excessive periods of time required to deliver EDP parts after the release date from USAAMC or 1st Logistical Command. Aircraft engines, transmissions and rotorblades have arrived at Direct Support Units (LSU) unaccompanied by necessary historical records and forms. This delays issue and/or installation of components until the paper work is located and reunited with the proper replacement part.
- (c) RECOMMEND.TION: Initiate a final pre-shipping inspection of aircraft components to insure all required historical records are included for shipment from AMC and Log Comd. Re-emphasize the urgency of EDP requisitions to Technical Supply support activities personnel, transportation command agencies and logistics unit commanders.

f. (C) Organization:

- (1) Fost Headquarters Camp Holloway:
- (a) OBSERVATION: Supervision of non-tactical administrative activities on Camp Holloway now requires a Post Headquarters Section of three officers, two AM and one civilian clerk.
- (b) EV.LUATION: The Post Headquarters Section is presently responsible for non-tactical services and logistical support for 23 tenant units or activities at Cam'n Holloway, including 10 units with a total of over 500 men, which are n. assigned to the 52nd CAB. These responsibilities include supervision of Officers, NCO and AM open mess; allocation of real estate; coordination of billeting; monitoring PX and consessionaire operations; supervision and coordination of base development; establishment and supervision of animal control; coordination of Engineer, Repair and Utilities activities, such as: electrical power supply and distribution, water supply and purification, fire prevention and control, post sanitation, work order requests, preventive maintenance, maintenance service orders and coordination of Pacific Architects and Engineers projects; maintenance of road nets; coordination of camp defense efforts, maintenance of perimeter security and lighting; supervision of library, craftshop and other Special Services activities; maintenance of law and order; supervision of health and dental activities; maintenance and police of the airfield; and the hiring and controlling of civilian employees. Repeated attempts to obtain MTOE or TDA authorizing a Post Headquarters Section to an installation where a combat aviation battalion is the senior occupant operating post, camp and station facilities have been unsuccessful. These administrative functions continue to be vital to the health, comfort, morale, discipline and security of over 2,300 tenants of this camp. The officers required to manage post activities must be drawn from aviation

AVGD-CC (5 November 1968)

SUBJECT: Operational Report of 52nd Combat Aviation Eattalion for Feriod Ending 31 October 1968, RCS CSFOR-65 (R-1) (U)

units, thus further aggravating the shortage of pilots available for cockpit duty. Enlisted personnel likewise hold TOE positions in units which are denied either productive work from the individual or a replacement for him. The following positions are considered essential:

DEPUTY FOST COMMANDER	0-4
FOST ENGINEER	0-3
CIVILIAN FERSONNEL/SPECIAL SERVICES OFFICER	0-3
ADMINISTRATIVE NCO	E-7
CLERK TYPIST/DRAFTSMAN	E-5

- (c) RECOMMENDATION: Solicit and submit MTOE, TDA or augmentation authority for a Post Headquarters Section to operate military posts such as Camp Holloway, Fleiku, RVN. Assign non-rated officers and qualified EM to these required positions now, pending approval of Post Headquarters authorization by competent authority.
 - (2) Unit Supply Officer:
- (a) OBSERVATION: The Assault Support Helicopter Company MTO1 1-258F is not authorized a unit supply officer.
- (b) EV.LU.TION: The Assault Support Helicopter Company, with 252 personnel 16 CH-47 and supporting ground equipment worth over \$18,000,000, is authorized only a Unit Commander and an Operations Officer in the Company Headquarters and Operations Sections. With neither Executive Officer nor Supply Technician authorized, a rated aviator must be taken out of the cockpit to perform supply and property book duties. The Assault Helicopter Company is authorized a trained warrant officer supply technician, MOS 761A, for these duties.
- (c) RECOMMENDATION: Modify the TOE of Assault Support Helicopter Companies to authorize a Supply Technician, MOS 761A.
 - (3) Combat Aviation Battalion Ammunition Officer:
- (a) OFSERVATION: The Combat Aviation Battalion, which is not authorized an ammunition officer, handles as much ammunition as a 8"/175mm Artillery Battalion.
- (b) EVALUATION: Requisition, accountability, distribution and control of the amount of ammunition necessary for basic load, base camp defense and combat operations by a Combat Aviation Battalian requires a fulltime Battalian Ammunition Officer to assist the S-4. The following comparison of ammunition expenditures during August, September and October 1968 is cited:

AVGD-CC (5. November 1968).

SUBJECT: Operational Report of 52nd Combat Aviation Battalion for Period Ending 31 October 1968, RCS CSFOR-65 (R-1) (U)

TYPE AMMUNITION	ARTILLERY BATTALION	AVI.TION BATTALION
175mm	10,500	0
90mm	240	. 0
81mm	198	1,412
66mm	25	6
40mm	796	10,543
8 inch	5,500	0
2.75 inch	0	6,767
.50 cal	840	. 0
.45 cal	, 1,000	1,400
.38 cal	0	3,400
7.62mm	27,900	1,678,920
5.56mm	100,640	43,025

- (c) RECOMMENDATION: Modify Combat Aviation Battalion Headquarters and Headquarters Detachment MTOE 1-76E to include a Battalion Ammunition Officer, 0-3, MOS 4510.
 - g. (C) Other: "Nestor Key Lists".
- (1) OBSERVATION: The 4th Infantry Division and the 52nd Combat viation Battalion operate from different "Nestor" key lists to obtain secure voice transmission capability.
- (2) EVALUATION: 52nd CAB aircraft supporting 4th Division units must operate with the supported unit's key. Aviators are then unable to communicate with their parent unit in the secure mode.
- (3) RECOMMENDATION: Division Signal Officers should distribute necessary key lists to non-divisional units operating in division nets, thus allowing uninterrupted secure voice capability on both supported unit and supporting unit Frequency Modulated radio nets.

3. Section 3. Headquarters. Department of the army Survey Information:

- a. (U) General: The Evasion, Escape and Survival Program of the 52nd Combat Aviation Battalion has been updated by a new Evasion, Escape and Survival annex to the Battalion Tactical SOF. This annex emphasizes unit responsibilities and procedures for the selecting and training of Evasion, Escape and Survival personnel, dissemination of survival information, use of EAE codes and maintenance of unit survival equipment at the company level.
 - b. (U) Evasion and Escape:



AVGD-CC (5 November 1968)

SUBJECT: Operational Report of 52nd Combat Aviation Battalion for Period Ending 31 October 1968, RCS CSFOR-65 (R-1) (U)

- (1) Case Histories: None.
- (2) School: The 52nd Combat Aviation Battalion has filled 15 allocations this period. All assigned companies have school trained Evasion and Escape Officers appointed on unit orders. Mach company has been encouraged to appoint an E&M NCO to assist the E&M Officer in the training of air crews. Debriefing of students returning from both the Navy and Air Force courses has produced favorable comments and results in the Battalion's Evasion and Escape Program. This has manifested itself in the increased training at unit level. The consensus of opinion among returnees favors the Air Force program and all students have suggested that it be lengthened. It is the policy of the 52nd Combat Aviation Battalion to participate in these courses whenever possible and that they enhance the E&M program throughout this battalion.
- c. (U) Survival: There have been no survival situations within this battalion for this period.

5 Incl

William C CHAMBERIAIN

LTC AT Commanding

DISTRIBUTION:

2 - CINCUSARPAU, ATTN: GFOP-DT, APO 96558

3 - CG, USARV, ATTN: AVHGC-DST, APO 96375

2 - CG, 1st Avn Bde, ATTN: AVBA-MN, APO 96384

7 - CO, 17th CAG, ATTN: AVGD-SC, APO 96240

AVGD-SC (5 Nov 68) lst Ind AUBJECT: Operational Report of 52d Combat Aviation Battalion for Period Ending 31 October 1968, RCS CSFOR-65 (RL) (U)

DA, Headquarters, 17th Combat Aviation Group, APO 96240 25 November 1968

To: Commanding General, I Field Fords Victum, ATTN: AVFA-GC-OT, APO 96350

- 1. (U) This headquarters has reviewed the basic letter from the 52d Combat Aviation Battalion. Pen and ink corrections of minor errors have been imported.
- 2. (3) This headquarters submits the following comments.
 - a. Section 1. Operations, pages 1 through 15: CONCUR.
 - b. Section 2, Lessons Learned.
 - (1) Paragraph 2a, Unit Strength Deficiencies, page 15:
- (a) CONCUR with the recommendation to program and assign replacements against known losses at all levels. Replacements lagged behind scheduled losses during the quarter, and the 52d Combat Aviation Battalion received its prorata share.
- (b) CONCUR with the recommendation to provide infantry units to assist in security of isolated aviation units. The 52d Security Platoon, an assigned group unit, currently covers the 30 square kilometer area of operation adjacent to Camp Holloway. This headquarters is preparing a letter requesting relief from the responsibility for that area of operation. Upon approval of the request, this headquarters will redeploy segments of the platoon to provide intermal and perimeter security for group units at Kontum, Holloway, and Ban Me Thuot.
- (2) Paragraph 2b(1), Briefings for Airmobile Operations, pages 15 and 16: CONCUR. Proper briefings should be SCP for all ground units. The 1st Aviation Erigade Operations Manual, dated 1 February 1967, discusses the briefing requirement in paragraph 11c(1), Chapter 12. Further recommend:
- (a) Revising the Brigade Operations Manual to include this briefing requirement in Appandix II, Airmobile Task Force Commander Charlest.
- (b) Placing increased emphasis on proper training and briefing of troops by supported ground commanders.
- Redumpd planning should be SOP for ground units in all airmobile operations. The late Atlanting Brigade Operations Manual discusses planning in paragraph 4, Section II, Chapter 3.

AVGD-SC (5 Nov 68) 1st Ind 25 November 1968
SUBJECT: Operational report of 52d Combat Aviation Battalion for Period
Ending 31 October 1968, RCS CSFGE-65 (RL) (U)

- (4) Paragraph 2b(3), Flechette Employment, pages 16 through 18:
- (a) CONCUR with the recommendation to provid a selective weapons system for the armed UH-IC aircraft.
- warheads. Message AVGD-SC 4801-68 (C), dated 20 October 1968, subject: 2.75 Flechette Warhead (U), to 1st Aviation Brigade, recommended a resupply rate of 1350 flechette rounds per month for this group. Message AVGD-SC 5182-68 (C); dated 17 November 1968, subject: Issue of WDU4A/A Warhead (U), to your headquarters, requested issue of 600 flechette rounds from USAF stocks for immediate use.
- (5) Paragraph 2b(4), AMCC, page 18: NONCONCUR. There are insufficient available fixed wing aircraft to conduct all missions required between fixed wing airfields. Neither the 52d Combat Aviation Battalion nor this head-quarters has the capability to properly analyze misuse of helicopter assets, since flying hours are the only available criteria upon which these echelons can base judgement. Recommend your headquarters conduct a continuing overall evaluation of employment of helicopter assets.
- (6) Paragraph 2c(1), UH-1 Emergency Procedures, pages 18 and 19: CONCUR.
 - (7) Paragraph 2c(2), New Equipment Qualification, page 19: CONCUR.
- (8) Paragraph 2d, Vietnames Civilian Control, pages 19 and 20: CONCUR, although the problem outlined has not been reported by other group units.
- (9) Paragraph 2e(1), Team Maintenance for AH-16 Aircraft, page 20: CONCUR.
 - (10) Paragraph 20(2), Forward Arua Aircraft Maintonance; page 21: CONCUR.
 - (11) Paragraph 2e(3); AH-IG Fluctuating Oil Prossure, page 21: CONCUR. Oil change at 25-hour intervals is recommended practice on all group AH-IG and UH-L aircraft.
- (12) Paragraph 2e(4), AH-IG Vibrations, pages 21 and 22: NONCONCUR, without further investigation. Other group units equipped with AH-IG aircraft report no vibration problems with M-1590 pods when aircraft is maintained within limits specified for the aircraft gross weight. The bulk of the pod mass extending forward from the wing appears to contribute to vibrations.

Confidential Confidential

- AVGD-SC (5 Nov 68) 1st Ind 25 November 1968
 SUBJ-ST: Operational Report of 52d Combat Aviation Battalion for Period
 Ending 31 October 1968, RCS CSFOR-65 (R1) (U)
- (13) Paragraph 2e(5), AH-1G/XM-159C Swaybrace Breakage, page 22: CONCUR. Unit has been instructed to submit an EIR on the problem.
- (14) Paragraph 2e(6), AH-IG Hydraulic Accumulator, page 22: CONCUR. However, TM 55-1520-221-20 outlines the hydraulic system bleeding procedure. Unit has been instructed to follow procedure in the manual or submit DA Form 2028 recommending a change thereto.
- (15) Paragraph 2e(7), Aircraft Parts, pages 22 and 23: CONCUR. The stated procedure is in effect at AMMC. Investigation indicates that delivery of large EDP parts may be delayed because of the lack of USAF shipping priority. Group units have been instructed to maintain records on all shipping delays of EDP parts.
 - (16) Paragraph 2f(1), Holloway Post Headquarters, pages 23 and 24:
- (a) CONCUR with the recommendation to solicit TDA authority. Unit will be directed by letter to submit request for TDA for Camp Holloway Post Headquarters under the provisions of USARV Circular 310-44 and USARV Regulation 310-49.
- (b) NONCONCUR with the recommendation to assign personnel against positions which, although required, are not authorized. Personnel can not be assigned against positions for which there are no TOE or TDA authorizations.
- (17) Paragraph 2f(2), Unit Supply Officer, page 24: CONCUR. Recommend no action pending DA publication of standard MTOE for the Assault Support Helicopter Company, which is expected to be in the near future.
- (18) Paragraph 2f(3), Ammunition Officer, pages 24 and 25: CONCUR. Recommend no action pending DA publication of standard MTOE for the Combat Aviation Battalion.
- (19) Paragraph 2g, Key Lists, page 25: CONCUR. This subject was discussed during a signal meeting at your headquarters on 19 June 1968. The USARV representative stated that a single key list had been considered for all units in the Republic of Vietnam, but the proposal was disapproved because of the ramifications of possible compromise. However, an agreement was reached whereby supported units would provide supporting units with key lists. The 4th Infantry Division has sufficient copies of key lists to implement the stated recommendation.

AVFA-GC-OT (5 Nov 68) 2d Ind SUBJECT: Operational Report of 52d Combat Aviation Battalion for Period Ending 31 October 1968, ECS CSFOR-65 (R1) (U)

DA, Headquarters, I Field Force Vietnam, APO 96350

TO: Commanding General, 1st Aviation Brigade, APO 96384

- 1. (U) This headquarters has evaluated subject report and indorsement and makes the following comments.
- 2. (C) Reference paragraph 2b(4), page 18, Area Movement Control Center. Nonconcur for reasons stated by the 17th Combat Aviation Group 1st Indorsement. This headquarters makes a daily review or avaluation of the employment of helicopter assets in the II CTZ.
- 3. (C) Reference paragraph 2e(4), pages 21 and 22, AH-1G Vibrations. Monconcur for reasons stated by the 17th Combat Aviation Group 1st Indorsement.
- 4. (C) Reference paragraph 2f(1), pages 23 and 24, Post Headquarters Camp Holloway. Nonconcur for reasons stated by the 17th Combat Aviation Group lat Indorsement.

FOR THE COMMANDED:

CPT. AGC

Asst AG

Cy furn: 17th Cbt Avn Gp

- AVRA-C (5 Nov 68) 3d Ind SUBJECT: Operational Report of 52d Combat Aviation Battalion for Period Ending 31 October 1968, RCS CSFOR-65, (R-1) (U)
- DA, HEADQUARTERS, 1ST AVIATION BRIGADE, APO 96384 1 7 DEC 1968
- THRU: Commanding General, United States Army Vietnam, ATTN: AVHGC-DST, APO 96375

 Commander-in-Chief, United States Army Pacific, ATTN: GPOP-OT, APO 96558
- TO: Assistant Chief of Staff for Force Development, Department of the Army, Washington, D.C., 20310
- 1. (C) This headquarters has reviewed this report, considers it to be adequate, and concurs with the contents as indorsed, except for the following:
- a. Paragraph 2b(3) (c), page 16. Nonconcur with recommendation to provide selective weapon system capability for the UH-1C armed helicopter. The total rocket load must remain the same due to weight limitations. The advantages to be gained with a selective system would be offset by the reduction in useable rockets available for close support if loaded with both types of rockets. Loading the UH-1C prior to take off gives those units equipped with the UH-1C the capability to use the flechette round.
- b. Paragraph 2c(2), page 19. Nonconcur. New Equipment Training Teams (NETT) are normally employed at unit locations to train a nucleus of instructor pilots who will subsequently train the remaining unit aviators. Current DA policy limits in-country AH-IG pilot transition training to that conducted at the USARV AH-IG School by the training team. The complexity of the AH-IG weapons systems and the requirements for conducting extensive ground school classes make it desirable to have the AH-IG training team permanently stationed at one central location. The current AH-IG aviator transition training, and the limited number of instructor pilots assigned to the USARV AH-IG training team, preclude field visits by the training team SIPs. Unit AH-IG SIPs and IPs are authorized to conduct IP standardization and check rides for aviators qualified in the AH-IG aircraft.
- c. Paragraph 2e(6), page 22. Nonconcur pending further investigation. TM 55-1520-221-20 prescribes bleeding the AH-IG emergency collective hydraulic accumulator system by use of the drain valve whenever it is necessary to check accumulator gas pressure and/or when pilot report or ground operational check reveals that emergency hydraulic power is not sufficient for four full strokes of the collective control stick.

1 7 DEC 1968

AVBA-C

SUBJECT: Operational Report of 52d Combat Aviation Battalion for Period Ending 31 October 1968, RCS CSFOR-65, (R-1) (U)

The Bell Technical Field Representative assigned to 34th General Support Group (Mr James Fergusen) and 34th GS Group Maintenance Office personnel know of no internal damage problem occurring as a result of bleeding the system only by pumping the collective after shutdown and coastdown; however, this observation will be investigated and if justification can be determined, the proper procedures will be published in the 34th GS Group Newsletter pending TM change publication.

- d. Paragraph 2f(2), page 24. Nonconcur. The standardized MTOE 1-258G for the Assault Support Helicopter Company will authorize a Company Executive Officer, 03, who could assume the duties as unit supply officer. The standardized MTOE 1-258G was submitted to DA proposing a Warrant Officer Unit Supply Technician, MOS 761A. This position was deleted from the advance copies of the MTOE received from DA. The unit supply technician position, MOS 761A, proposed for the Assault Helicopter Company standardized MTOE 1-77G was also deleted from the advance copies.
- e. Paragraph 2f(3), page 24. Nonconcur. An E5 Ammunition Sergeant, MOS 55B40, has been added to the Battalion S-4 section in the standar-dized MTOE 1-256G. This NCO position is considered adequate to assist the Battalion S-4 in the requisitioning, accountability, distribution and control of necessary ammunition used by a Combat Aviation Battalion.
- 2. (C) The following additional comments are considered pertinent:
- a. Paragraph 2c, page 18. Standardization/training rides conducted in USARV include anti-torque control failure training. In most cases, this training is the first of this type that the aviators receive. Training must, however, be limited to the anti-torque control failure since other types of failure cannot be simulated.
- b. Paragraph 2e(5), page 22. This headquarters and USARV are aware of the problems with sway braces. EIRs have been submitted by the 52d Combat Aviation Battalion.
- c. Paragraph 2f(1), page 23 and 24. Concur with basic letter. Unit has been advised to submit a proposed TDA.
- d. Paragraph 2b(2)(a), page 27, 1st Indorsement. The 1st Aviation Brigade Operations Manual is currently under revision. Safety briefings for personnel boarding or departing helicopters will be included in the AMTF Commander's Checklist.

AVBA-C
SUBJECT: Operational Report of 52d Combat Aviation Hattalion for Period
Ending 31 October 1968, RCS CSFOR-65, (R-1) (U)

e. Paragraph 2b(4)(b), page 28, 1st Indorsement. Recommended supply rates from subordinate units are consolidated at this headquarters and forwarded to Headquarters, USARV.

FOR THE COMMANDER:

LEE S. PETERSON

1LT, AGC

ASST ADJ GEN

AVHGC-DST (5 Nov 68) 4th Ind (C)

SUBJECT: Operational Report of 52d Combat Aviation Battalion for Period Ending 31 October 1968, RCS CSFOR-65, (R-1) (U)

HEADQUARTERS, UNITED STATES ARMY, VIETNAM, APO San Francisco 96375

- TO: Commander in Chief, United States Army, Pacific, ATTN: GPOP-DT, APO 96558
- 1. (U) This headquarters has reviewed the Operational Report-Lessons Learned for the quarterly period ending 31 October 1968 from Headquarters, 52d Combat Aviation Battalion.
- 2. (C) Comments follow:
- a. Reference item concerning employment of WDU-4 A/A flechettes, page 16, paragraph 2b(3); and 3d Indorsement, paragraph la: Concur with 3d Indorsement, paragraph la.
- b. Reference item concerning new equipment qualification, page 19, paragraph 2c(2); and 1st Indorsement, para 2b(7); and 3d Indorsement, paragraph 1b: Concur with 3d Indorsement, paragraph 1b.

FOR THE COMMANDER:

W. C. ARNTZ

CPT. AGC

Assistant Adjutant General

Cy furn: HQ lst Avn Bde HQ 52d CAB

> *35* Confidential

GPOP-Df (5 Nov 68) 5th Ind (U) SUBJECT: Operational Report of HQ, 52d Cbt Ave En for Period Ending 31 October 1968, ECS CSFOR-65 (R1)

KQ, US Arwy, Pacific, APO Sam Francisco 96358

35 JAN 1969

TO: Assistant Chief of Staff for Force Development, Department of the Army, Washington, D. C. 20310


This headquarters has evaluated subject report and forwarding indorsements and concurs in the report as indorsed.

FOR THE COMMANDER IN CHIEF:

G. L. SHORTT

Ass AQ

52D COMBAT AVIATION BATTALION ORGANIZATIONAL CHART



Incl 1

ORGANIZATIONAL STRUCTURE AND STATION LIST

UNETO a second	O MANDER	LOCATION	APO
52d Cbt Avn Bn "FLYING DRAGONS"		Camp Holloway Pleiku, RVN	96318
Hq & Hq Det 52d Sec Det 68th Rdr Det 94th Med Det		Camp Holloway	96318
57th Aslt Hel Co "GLADIATORS"	MAJ Robert M. Williams	City Airfield, Kontum, RVN	96499
615th TC Det 882nd Sig Det	CPT Silas E. Beck CW2 Bernard J. Leftault		•
119th Aslt Hel Co "ALLIGATORS"	MAJ Kenneth R. Cary	Camp Holloway Pleiku, RVN	96318
545th TC Det 70th Sig Det	1LT Ronald . Dean CW2 Floyd V. Garrison	1.1	
170th Asit Hel Co "BIKINIS"	Maj Donali A. Roberts	Camp Holloway	96318
405TH TC Det 448th Sig Det	MAJ Edward D. King		
179th Aslt Spt Hel Co	MAJ Donald E. Holroyd	Camp Holloway Paciku, RVN	96318
402nd TC Det	MAJ Claire E. Book).	
189th Aslt Hel Co "GHOST AIDERS"	Mail Robert N. Morrison	Comp. Holloway Pleiku, RVN	96318
604th TC Det 6th Sig Det	CW2 Ronald L. Collins		
361st Avn Co (E)		Camp Holloway Pleiku, RVN	96318
665th TC Det 621st Sig Det	CPT George Michel (None Authorized)	ţ	
OPCON: 1st Plt, 355th Avn Co (Heavy Helicopter) "WORK HORSE"	CPT John Geuran	Cemp Holloway Plaiku, RVN	9 6318

Incl 1

UNIT STRENGTH AS OF 31 OCTOBER 1968

1. (C) Mili	tary:
-------------	-------

(o) military		0	•	WO	E	M	TO	TAL
UNIT	AUTH	<u>ÁచેG</u>	AUTH	ASG	AUTH	ASG	AUTH	ASG
HHD	22	20	2	5	87	101	111	126
94th Med Det	1	1	•	0	8	8	9	9
755th Med Det	1	1	0	0	8	9	9	10
52d Sec Dat	1	2	0	0	151	<u> </u>	152	96
68th Inf Det	0	0	0	0	19	14	19	14
57th AHC	15	14	5 2	43	152	129	219	186
615th TC Det	1	1	1	1	79	43	81	45
822 Sig Det	Q	0	1	1	8	7	9	3
119th AHC	15	14	52	43	152	129	219	186
79th Sig Det	1	0	O	1	9	8	10	9
545th TC Det	1	1	1	1	70	48	72	50
170th AHC	15	16	52	37	152	125	219	178
405th TC Det	1	2	1	0	70	45	72	47
448th Sig Det	0	0	1	1	8	6	9	7
179th ASHC	13	6	25	18	132	128	170	152
402d TC Det	1	1	1	1	80	69	82	71
189th AHC	15	14	52	36	152	129	219	179
6th Sig Det	0	1	1	G.	8	6	9	7
604th TC Det	1	0	1	1	70	48	72	49
361st AC (E)	16	12	14	9	82	55	112	76
621st Sig Det	0	0	O	0	6	6	6	6
665th TC Det	1	1	1	1	56	45	58 5	47
52D CAB	121	107	258	199	1559	1252	1938	1558

2. (G) <u>Civilian</u>:

	DA	DAC		<u>N</u>	<u>3</u> d	3d NAT	
UNIT	AUTH	ASG	AUTH	ASG	AUTH	ASG	
52d HHD 57th AHC 119th AHC 170th AHC 179th ASHC 189th AHC 355th AC (HH) (1PLT) 361st AC (E)	0 0 0 0 0 0 0 0 0	0 0 0 0 0 0 0	26 14 12 9 9 9 3 3	24 11 11 9 9 9 0	0000000	0000000	
52D CAB	0	0	85	75	0	0	

Incl 2

39

OPARATIONAL RESULTS AS OF 31 OCTOBER 1968

1. (C) Res	ults:		CARGO					
UNIT	SORTIES FLOAN	TROOPS LIFTED	LIFTED (TONS)	ENEMY KBA	STRU DAM	CTURES DEST	SAM DAM	PANS DEST
57 AHC	26,136	27,889	812	59	0	0	٥	0
119 AHC	15,770	18,894	621	0	C	0	0	٥
170 AHC	6,721	8,278	241	0	0	0	0	0
179 ASHC	7,458	16,665	12,119	0	0	0	.0	0
189 AHC	25,717	27,134	598	25	10	10	10	o
355 AC (HH)	2,456	0	524	0	0	0	Ö	0
361 AC (E)	2,660	30	0	19	8	4	0	0
HHD	949	52	2	0	0	0	0	0
52 CAB	88,107	98,942	14,917	103	18	14	10	0

2. (C) <u>Losses</u>:

<u>UNIT</u>	AIRCHAFT TYPE	LOST NR	AIRCRAFT D	AMAGED
57 AHC			UH-1 C UH-1H	5 10
170 AHC	UH-1C UH-1H	3 1	uh-1c uh-1h	2 2
179 ASHC	CH-47	2		
189 AHC	UH-1H	2	UH-1C UH-1H	4
361 AO(E)			AH-1G	
52 CAB	•	8		25

Incl 3

40 COMFIRENTIAL AIRCRAFT STATUS AS OF 31 OCTOBER 1968

1.	(C)	AH-1G	CH-47	TH-1C	UH-1D	UH-1 H	TI-6A
UNI	ŗ	Auth/OH	Auth/OH	Auth/OH	Auth/OH	Auth/OH	Auth/OH
- - 5 7	AHC	·	•	8/8	·	23/19	
119	AHC			· 8/7	• ,	23/20	,•
170	AHC			8/6		23/19	,
179	VHC		16/14				
189	AHC	·	•	8/8		23/20	
361	AC (E)	12/12		•	•		
HHI)				2/1	•	1/1
52	CAB	12/12	16/14	32/29	2/1	92/78	· 1/1

2. (C) AIRCRAFT AVAILABLE, MISSION READY, EDM AND EDP (DAILY AVERAGE)


	STAMD/RD (%)	AUG	,	SKP	OCT.
		1 '	AH-1G		• /
Availability	'70	68:0	····	60.4	68:0
Mission Ready	N/V	62.6	• •	56 .1	61.7
PEM	N/A	23.0		24:7	14.5
EDP	N/V	9.0		14.9	17.5
			CH-47		. • /
Availability	65	65:0		59:n	'58 <u>.</u> ' ∩
Mission Ready	N/V	59.2		54:4	56:2
EDM	23	23.0	•	27:0	31:0
EIDP	12	12.0		14.0	11.0
			ਹਜ –1 C		, •
Availability	75	76:5		73:1	75:1
Mission Ready	N/A	65.9		61:4	54:0
EDM	17	49.3		20.5	19:7
EDP	8	4.2		6,4	5.2
		,	UH-1 H	. •	
Availability	78	78:3		74:6	75:5
Mission Ready	$\Lambda \backslash N$	72:6		65:6	60 : 6
EDM	17	17.0		19.8	17:6
EDP.	5	4.7		5.6	6.9

Incl. 4

3. (C) RECAPITULATION OF FLYING HOURS

UNIT	MONTH	AVG. NR.	HOURS	AVG. HRS	AVAIL-	PERCENT.
		ON HAND	FLOWN	PER ACET	ABILITY	DA PROGRAM
			n.H-	1G		
361st	Aug.	12.0	626	52,1	63.6	74%
	Sep	12.0	539	44.9	60.4	64%
	Oct	12.0	621	51.8	68.0	74%
			CH-	47		
79th	Aug	16.0	880	55.0	65.0	91%
	Sep	14.5	778	53.7	59.0	89%
	Oct	13.7	910	66.4	58.0	111%
			UH-	1C		
57th	Aug	8.0	519	64.8	73.0	100%
	Sep	8.0	434	54.2	80.2	9 3 %
	Oct	8.0	396	49.5	86.0	85%
119th	Aug	8.0	410	52.1	76.2	88%
•	Sep	8.0	318	39.7	67.9	68%
	Oct	7.6	289	30.8	71.8	53%
170th	Aug '	8.3 -	412	49.6	79.8	86%
, , , , , , , ,	Sep	8.0	652	81.5	76.2	140%
	Oct	7.5	476	60.3	76.3	104/5
189th	Aug	7.8	317	40.6	76.7	70%
	Sep	7.8	283	36.2	68.2	6 2 %
	Oct	7.4	441	59.6	66.2	103%
2nd	Aug	32.1	1658	51.5	76.5	88%
(Over	Sep	31.8	1687	53.0	73.1	91%
<u> </u>	Oct	30.5	1602	52.5	75.1	91%
				-1H	And the second second	والمستون والمستون والمستون والمستون
57th	Aug	21.0	2305	109.7	83.2	148%
71 944	Sep	21.0	2047	97.5	76.9	131%
	Oct	19.9	1759	80.8	36.8	103%
119th	Aug	21.0	1411	67.1	68.8	90%
11701	Sep	19.9	1275	65.1	74.0	88%
	Oct	19.6	1421	72.5	62.2	98%
170th		19.9.	1708	85.3	85.0	115%
1 / G GII	Aug	20.0	2018	100.9	81.0	136%
	Sep		2013		80,3	137%
100+1	Oct	18.3	1286	110.0	76.1	103%
189th	Aug	20.Q		64.3		37%
	Sep	19.4	1256	64.7	96.7 72.5	104%
****	Oct	19.5	2053	105.3	78.3	92%
52nd	Aug	81.9	6713	68.6		110%
	Sep	80.3	6596	82.1	74.7	103%
	Oct	77.3	7246	93.7	74.5	103/6
	TYPE	HOURS FLO		AVAILAB		
	ACFT	Aug Sep	Oct	Aug	Sep Oct	
HHD	UHID	42 29	.38	100%	55% 90%	
-	U-6A	26 51	25	92,6%	98.6% 80.6%	
#Der	ertment of	the Army Pro	gramed Fl	ying hours p	er aircraft po	er month:
	<u>AH-1G</u>	' CH-		UH-1C	<u>UH-1H</u>	
	70	6	0	58	74	

Incl 4



CONFIDE CONFIDENTIAL

 	-		
Teached t	w C1	and fi	

	CONTROL DATA - R	•
(Security classification of title, body of abstract and to ORIGINATING ACTIVITY (Corporate author)	indusing armotation must be	entered when the overall report is classified) Za. REPORT SECURITY CLASSIFICATION
		CONFIDENTIAL
HQ, OACSFOR, DA, Washington, D.C. 20	0310	25. GROUP
Operational Penert Leggers Le	ewnod Ua 50nd	Combat Assistion Pottolion
Operational Report-Lessons Le Period Ending 31 October 1968		compac Aviation Battation,
Totalog = Hotalog 5x 0000001 1900		
4. DESCRIPTIVE HOTES (Type of report and inclusive dates)		
Experiences of unit engaged in counters. Author(s) (Pirel name, middle initial, last name)	erinsurgency_oper	rations, 1 Aug - 31 Oct 68
CO, 52rid Combat Aviation Bat	talion	
S. REPORT DATE	70. TOTAL NO.	OF PAGES 76. NO. OF REFS
5 Nov 68	46	
M. CONTRACT OR GRANT NO.		N'S REPORT NUMBER(5)
b. PROJECT NO.	68	4159
•		
c. N/A	Sb. OTHER REP	ORT NO(3) (Any other numbers that may be essigned
		,
d.		
10. DISTRIBUTION STATEMENT		·
11. SUPPLEMENTARY NOTES	12. SPONSORIN	G MILITARY ACTIVITY
N/A	OACSFOR,	DA, Washington, D.C. 20310
13. ABSTRACT		
	•	•
		•
'		•
	,	
		•
And the second s		
•		• •
	y .	
,		WAREHA REPORTED
	· ·	
	•	•
	AA	
t e e e e e e e e e e e e e e e e e e e	T 1.	

DD FORM 1473

UNCLASSIFIED

Security Classification